

WT-3000 WRIST STRAP TESTER**I. Description**

The WT-3000 tester is a convenient unit for testing ESD control wrist straps. The tester also has a "Low Battery" indicator. The tester operates on a 9-volt battery. A battery is included with the unit. Alternately the unit can be powered by a 7.5 Volt 0.1 Amp adapter (not supplied).

II. Contents

1 test unit with 9v battery

III. Verification: Verification should be performed annually. Verification is available from Static Technologies' headquarters.

IV. Specification:

Dimensions (tester only): 2-3/4" x 3-1/2" x 1"

Power supply: One 9V alkaline battery

Wrist strap test limit – lower: 800,000 ohms

Wrist strap test limit – upper: 10 megohms

V. Use Instructions

To test the wrist strap the user simply inserts the ground end of the wrist strap to the banana jack on the tester. With wrist strap on, firmly press the metal button on the meter. Buzzer will sound first. If the wrist strap is functioning properly the green LED will light, buzzer will stop. If the wrist strap is failing "high", yellow LED and buzzer indicate failure. If the wrist strap tests "low", red LED and buzzer indicate failure.

All statements, technical information and recommendations related to the seller's products are based on information believed to be reliable, but the accuracy or completeness thereof is not guaranteed. Before using the product, the user should determine the suitability of the product for its intended use. The user assumes all risks and liability whatsoever in connection with such use.

Static Technologies Corporation ♦ 61 Pleasant Street ♦ Randolph, MA 02368 U.S.A.

Telephone: 781-961-7220

Email: statictech@xensei.com

Fax: 781-961-1858

Website: www.static-tech.com